

Size Chart

How to measure

A - Center Back Length

Measure on back, from bottom of collar to the bottom (hem) of the jacket.

B - Chest Circumference

Measure around chest on widest point.

C - Mid Circumference


Measure around the waist on smallest point.

D - Bottom Circumference

Measure around the bottom of the jacket.

E - Sleeve

Measure from the neck, all the way down the arm.



Size Chart // Mens Oslo Coat

Product Outside Measurements. All measurements in cm

	A	B	C	D	E
Size	Center back Length	Chest	Waist Circumference	Bottom Circumference	Sleeve length from shoulder
S	85	108	106	110	79
M	87	114	112	116	81
L	89	120	118	122	83
XL	91	126	124	128	85
2XL	93	132	130	134	87

