Size Chart

How to measure

A - Center Back Length

Measure on back, from bottom of collar to the bottom (hem) of the jacket.

B - Chest Circumference

Measure around chest on widest point.

C - Mid Circumference


Measure around the waist on smallest point.

D - Bottom Circumference

Measure around the bottom of the jacket.

E - Sleeve

Measure from the neck, all the way down the arm.



Size Chart // Womens Oslo Coat

Product Outside Measurements. All measurements in cm

	А	В	С	D	Е
Size	Center back Length	Chest	Waist Circumference	Bottom Circumference	Sleeve length from shoulder
S	77	98	94	104	74
М	79	104	100	110	75
L	81	110	106	116	76
XL	83	116	112	122	77
2XL	85	122	118	128	78

